

10/518194

1/10




Fig. 1




Fig. 3





Fig. 4



10/518194

4/10

Fig. 5




Fig. 6





Fig. 7



10/518194

6/10

Fig. 8





Fig. 9



7/10

Fig.10





Fig.11



10/518194

8/10

Fig.12





Fig.13



10/518194

9/10

Fig.14





Fig.15



10/518194

10/10

Fig.16

The results of measuring the carrying tensions (Comparative Example 4)




Fig.17

